

From: SUNDARAJAN Narayan [mailto:Narayan_SUNDARAJAN@rta.nsw.gov.au]
Sent: Tuesday, 14 October 2008 7:23 AM
To: Olsen, Peter M
Subject: RE: Peakhurst Public School Northbound Sign (FL0103) Faulty

Peter

Thanks for that. Regarding the test switch, I had a call later on yesterday from the RTA technician stating that there was some misunderstanding and they had not replaced the switch yet, but as per my instruction will visit site on 14 Oct 08 and replace it.

Now that you have replaced it I will record it in my database as such and close the issue.

Thanks and Regards,

Narayan Sundarajan
ITS Projects
Mob: 0417 462 795
Phone: (02) 8837 0224
Fax: (02) 8837 0044

From: Olsen, Peter M
Sent: Tuesday, 14 October 2008 6:46 AM
To: SUNDARAJAN Narayan
Subject: RE: Peakhurst Public School Northbound Sign (FL0103) Faulty

The northbound sign at Peakhurst Public, FL0103, is and was working perfectly. It was the RTA supplied and installed RCD safety switch that had tripped, similar to the problem we had previously with one of the signs at Peakhurst West Public. I checked the controller but there was nothing wrong with it that could have caused the problem. I will keep an eye on it to make sure that it is not a regular occurrence.

I also changed the test switch on the sign on Isaac St near Peace Ave. The old switch had NOT been replaced since we inspected it in March. It was the exact same broken switch that was there from the beginning. That I can prove.

From: SUNDARAJAN Narayan [mailto:Narayan_SUNDARAJAN@rta.nsw.gov.au]
Sent: Monday, 13 October 2008 2:16 PM
To: Olsen, Peter M
Subject: FW: Peakhurst Public School Northbound Sign (FL0103) Faulty

Peter

I just now discussed with the RTA technician who said that he did replace the faulty test switch as per your suggestion sometime back.

As you have raised the issue again I have requested him to visit site and replace the test switch for the sign on Issac Street near Peace Avenue.

I have registered this as an issue and once completed will let you know so the issue can be closed.

Thanks and Regards,

Narayan Sundarajan
ITS Projects
Mob: 0417 462 795
Phone: (02) 8837 0224
Fax: (02) 8837 0044

From: Olsen, Peter M
Sent: Monday, 13 October 2008 12:32 PM
To: SUNDARAJAN Narayan
Subject: RE: Peakhurst Public School Northbound Sign (FL0103) Faulty

I will attend to it this afternoon. I checked all lights on the weekend and they appeared to be ok.

I did notice that the sign on Isaac St near Peace Ave still has a faulty test switch on the controller. I pointed it out to the RTA technicians when we were there in March checking the end of daylight savings and they said they would replace it. That was over 7 months ago.

From: SUNDARAJAN Narayan
[\[mailto:Narayan_SUNDARAJAN@rta.nsw.gov.au\]](mailto:Narayan_SUNDARAJAN@rta.nsw.gov.au)
Sent: Monday, 13 October 2008 12:12 PM
To: Olsen, Peter M
Subject: Peakhurst Public School Northbound Sign (FL0103) Faulty

Peter,

RTA Surveyor has reported that the School Zone Sign (FL0103) at Peakhurst Public School on Bonds Road (Peakhurst) is not working.

As RTA technician is not familiar with your control system, could you please rectify the faulty sign.

If there are any issues then please contact me on 88370224.

Thanks and Regards,

Narayan Sundarajan
ITS Projects
Phone: (02) 8837 0224
Fax: (02) 8837 0044
Mob: 0417 462 795